

CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA 094 Date of Visit: 8.12.2020

Contractor Personnel on Site:

1. _____
2. _____
3. _____
4. _____
5. _____
6. _____

Service Call Number

CSS# _____ WO# 12594


Description of Repairs

Found Evap flow sensor faulty. Ordered parts, picked up parts from Richmond. Removed faulty parts. Installed new sensor/ Sequence-5- LED (BAC) cable. Tested chiller operations. Chiller is cooling.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Richard Walker Date: 8.12.2020

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Donald Hysen Date: 8.12.2020

Signed: 

E-Mail: _____



5-motion sensors

1-door keypad

no internal cameras

2-cages (LG magnetic door sensor on each cage)

1-LG magnetic sensor on vault door

No- vault lock change

1- dehumidifier inside vault (hard wired)

1-Advantor cabinet (2-7AH Batteries)