

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA001 Date of Visit: 12/7/24

Contractor Personnel on Site:

1. Aaron Skeens 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO17384 Burnham Low Pressure Boiler Flame Sensor Failure.

Service Calls – Service Call Number and Description

1. CSS# 2966272
2. CSS# No change in Flame color, but looks a little unstable.
3. CSS# Flame starts to sputter and cannot keep lit. All safety's have been tested with no issues. Reccomend Casto Mechanical for further investigation.



-AS

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Aaron Skeens Date: 12/7/24

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.
This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Amy Choate Date: 12/7/24

Signed: 

E-Mail: _____

