



## CERTIFICATION OF WORK


(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV005

Date of Visit: 21-MAY-2025

Contractor Personnel on Site:

1. Aaron Skeens



### Work Performed:

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO18557 WO18639 WO18734 WO18735 WO18699 MAY PM



### Service Calls – Service Call Number and Description

1. CSS# All filters have been changed and FE check out well.
2. CSS# Asset #3044 Reznor Air Handler has been abandoned.
3. CSS# Through wall AC, Air Curtain, Air Compressor PM complete. Full PM on furnace complete as well. No issues.

-AS

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Aaron Skeens Date: 21-MAY-2025

Signed:



To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.

This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Wesley Thomsen Date: 21-MAY-2025

Signed:



