

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA001 Date of Visit: 17-DEC-2025

Contractor Personnel on Site:

1. Aaron Skeens 2. \_\_\_\_\_

### Work Performed:

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO20748 main pump isn't working and roof cap leaking water

### Service Calls – Service Call Number and Description

1. CSS# Water circulating pump is not operating and seized up.
2. CSS# Roof cap has been reseated and sealed to prevent water leaking,
3. CSS# Repair made did not fix leaking flue. Pump will need replaced.

Reccomend outsourcing to Casto Mechanical.  
-AS

---

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Aaron Skeens Date: 17-DEC-2025

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.

This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: SGT Diamond Date: 17-DEC-2025

Signed: 

E-Mail: \_\_\_\_\_

