

# U.S. CRANE, INC.

CRANES, HOISTS: PARTS & SERVICE  
(800) 466-8224 (513) 530-5252

DATE 8/30/2023

WORK ORDER #: 33106 -38720

CUSTOMER: CMI MANAGEMENT, INC. (U.S. ARMY RESERVE)  
6467 MIKE WOOD BLVD  
CONNEAUT LAKE PA 16316

JOB CMI MANAGEMENT, INC. (U.S. ARMY RESERVE)  
LOCATION: 6467 MIKE WOOD BLVD (PA118)  
CONNEAUT LAKE PA 16316

CUSTOMER ORDER #: REGINALD COOK

CONTACT: REGINALD COOK

PHONE #: 703-738-5307

DATE REQUIRED: SEPTEMBER 2023

## INITIAL DESCRIPTION OF PROBLEM OR REPAIRS TO BE DONE:

ANNUAL OSHA MAINTENANCE INSPECTION OF (1) OVERHEAD CRANE AND HOIST

U.S. ARMY RESERVE - CONNEAUT LAKE  
REGION 4A - PA118

GARAGE - HIGH BAY, CR1  
MONORAIL W/ HOIST & TROLLEY  
SHAWBOX 10 TON

**MUST FILL OUT COW AND TAKE PICTURES OF ANYTHING FOUND  
INCLUDES 26' SCISSOR LIFT TO AND FROM JOBSITE**

ABOVE COMPLETED: YES ☒ NO ☐ ALL PARTS USED: YES ☐ NO ☐

## DESCRIPTION OF ADDITIONAL WORK DONE AND PARTS USED :

IF ADDITIONAL WORK IS NOT RELATED TO ABOVE, A NEW WORK ORDER IS REQUIRED.

SERVICE AND PARTS STILL NEEDED:

CUSTOMER ACTION PRIORITY: ☐ HIGH ☐ MED ☒ LOW

**INSPECTION LIST ON SERIAL #: 98D13713**

☒ WIRE ROPE OR CHAIN CONDITION  
☒ CHAIN OR CABLE CONNECTIONS  
☒ ROPE REEVING  
☒ HOIST HOOKS & LATCH  
☒ LIMIT SWITCHES  
☒ BRAKES

☐ SLINGS  
☒ PROPER OPERATION  
☒ ALL FUNCTIONS  
☒ WARNING DEVICES  
☒ OVERALL CONDITION  
☒ CONTROLS

☒ P.B. STATION/CORD  
☒ DISCONNECT SWITCH  
☐ FESTOON SYSTEM

**REMOVE FROM SERVICE:**  
☐ YES ☒ NO

**COMPLETE FUNCTIONAL TESTING OF ALL APPLICABLE ITEMS**

TECHNICIAN SIGNATURE: [Signature]

SO # S-11562

CUSTOMER SIGNATURE: [Signature]

TODAY'S DATE: 9-29-23



### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA 118 Date of Visit: 9-29-23

Contractor Personnel on Site:

1. Brian Snyder
2. Cory Snyder

#### Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. Annual OSHA crane inspection

#### Service Calls – Service Call Number and Description


1. CSS# 95368
2. CSS# \_\_\_\_\_
3. CSS# \_\_\_\_\_

---

### CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Brian Snyder Date: 9-29-23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed. This is **NOT** a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Ben Shields Date: 2023/09/29

Signed: 

E-Mail: benjamin.l.shields.civ@army.mil