

**CERTIFICATION OF WORK  
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: DE002

Date of Visit: 11/20/2020

Contractor Personnel on Site:

1. Abe Patz

3. \_\_\_\_\_

2. \_\_\_\_\_

4. \_\_\_\_\_

**Work Performed:**

**Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)**

1. WO 13098 Asset 190918-131

2. \_\_\_\_\_

3. \_\_\_\_\_


4. \_\_\_\_\_

5. \_\_\_\_\_

**CERTIFICATION OF WORK**

To be signed by the Contractor:


Print Name: Abe Patz Date: 11/20/2020

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Castellanos, Hector Date: 2020 Nov 20

Signed: 

E-Mail: \_\_\_\_\_

Tidewater, INC  
DE-002  
1137 Savannah Rd.  
Lewes DE 19958  
(410) 540-8700

Recorded By: Jon Miller  
(301) 580-9820  
jmiller@bondwater.com

**Boiler Room - HVAC Equipment**

Test	Hot Loop			
Conductivity (as mmhos)	200 3500 max			
pH	8.0 8 - 10.5			
Molybdate (ppm as Mo)	40 40 min			

**Opening Comment**

Performed bi-annual scheduled service visit.

Service was performed by Abe Patz.

**Hot Water Loop****Online** 

All readings indicate good levels of protection for closed system. System lost a good amount of treatment but still has a good amount of corrosion inhibitor present.