

**Region:** 5

**Location:** DE007

**CSS #:** 30954

**Maximo Work Order No.:** 14523

**Asset #:** NA

**Date Issued:** 7/9/21

**Original Description:** There are about 15 emergency lights not working. These were recently tested and were working fine. The fact that most of these lights are right in a row, I think an electrical surge may have been the cause. Not sure if the batteries are dead or if it's something else.

**Repairs Needed:**

Labor and materials to replace 150 emergency light batteries.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	6V DC, Sealed Lead Acid Battery	--	--	\$7,230.00	--	\$7,230.00
--	NA	TWI Labor (Includes Diagnostic)	10	\$80.00	--	--	\$800.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
10	\$800.00	\$7,230.00		\$8,030.00	106%	<b>\$8,511.80</b>

# WORK ESTIMATE

 CSS #: 30954

 Work Order #: 14523

 Emergency 

 Urgent 

 Routine X

Company Name:	Tidewater, Inc.		Facility ID:	DE007
Contractor POC:	Adam Colopy			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net			
Assigned Technician(s):	John Brown			

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 150 emergency light batteries.

LABOR/MATERIAL		MATERIAL/SU B UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
6V DC, Sealed Lead Acid Battery	150	\$48.20		\$7,230.00
Labor			8	\$640.00
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>\$7,230.00</b>	<b>Labor</b> <b>\$800.00</b>
		<b>TOTAL</b>		<b>\$8,030.00</b>

## My Products

## Reference Information

### GRANINGER APPROVED



6V DC, Sealed Lead Acid  
Battery, 12 Ah, Faston, 3.7 in  
Height, 4.18 lb Weight, 6.0 in


Item # 2408



150  
= 0.0  
= 0.0

Your Price

\$38.25 / each



Item #

2408

6V DC

Sealed

Lead Acid

6V DC

Sealed

Lead Acid

Central Coast Library Board is unable to provide  
any requested information.  
Anita Van Winkle, Library Co-Director  
Central Coast Library Board  
15151 Hwy 101  
Pismo Beach, CA 93450  
(805) 734-4771  
Fax: (805) 734-4772  
e-mail: [anita.vanwinkle@pismo.k12.ca.us](mailto:anita.vanwinkle@pismo.k12.ca.us)  
http://www.pismo.k12.ca.us/centralcoastlibrary



**IMPORTANT: BATTERY MUST BE RECHARGED WITHIN 6 MONTHS FOR LEAD ACID / 12 MONTHS FOR NICAD OR NiMH. IF UNIT IS NOT IN SERVICE, STORE AT TEMPERATURES UP TO 40°C. THIS UNIT CONTAINS A BATTERY THAT IS MAINTAINED WHEN REORDERING, SPECIFY BATTERY AND MODEL # DO NOT DISPOSE OF IN LANDFILLS OR INCINERATORS. RECYCLE WITH AUTOMOTIVE BATTERY SCRAPS OR RETURN TO MANUFACTURER.**

**CAUTION: OBSERVE POLARITY**

