



## General QC Inspection - Army Corps Region 5

19 Sep 2022 / Richard Hicks

Complete

**Conducted on**

19.09.2022 14:59 EDT

**Prepared by**

Richard Hicks

**Location**

DE007-01 Newark , Delaware

Boiler Installs

## Quality Control Inspection Checklist

Date/Time:

19.09.2022 09:00 EDT

Building:

Mechanical Room

Room/Area:

Boiler's Install

Inspector:

QC

Inspection Type:

Scheduled

Service Call/Work Order Inspections:



Preventative Maintenance/Work Order Inspections:



Work Order/PM Number:

WO#17328

Boiler Status Updates Day 1- Demo day- New Boilers set in place



Photo 1



Photo 2



Photo 3




Photo 4



Photo 5




Photo 6



Photo 7



Photo 8




Photo 9




Photo 10




Photo 11



Photo 12



Photo 13



Photo 14

Work Order/PM Number:

WO#17328

Boiler Status Updates Day 2. Plumbing and control wiring




Photo 15




Photo 16




Photo 17



Photo 18

Work Order/PM Number:

WO#17328

## Boiler Status Updates Day 3 Progress



Photo 19




Photo 20



Photo 21



Photo 22




Photo 23



Photo 24

---

**Work Order/PM Number:**

WO#17328

## Boiler Status Updates Day 4 Worked on landing control wiring



Photo 25

---

**Work Order/PM Number:**

WO#17328

## Boiler Status Updates Day 5 Factory start up confirmed for 9/28



Photo 26




Photo 27




Photo 28



Photo 29



Photo 30

---

**Work Order/PM Number:**

WO#17328

## Boiler Status Updates Day 6 Getting ready for factory start up 9/28




Photo 31




Photo 32



Photo 33



Photo 34



Photo 35

---

**Work Order/PM Number:**

WO#17328

## Boiler Status Updates Day 7 Update pictures



Photo 36




Photo 37




Photo 38




Photo 39



Photo 40




Photo 41

---

**Work Order/PM Number:**

WO#17328

Boiler Status Updates - Factory Boiler start up completed October 7,2022-See start up video Boilers online

[IMG 1076.mov](#)

**Were all Safety Procedures followed?**

Yes

## **Additional Remarks:**

CERTIFICATION OF WORK

**Inspection Results:**

Pass

**Date/Time:**

07.10.2022 12:59 EDT

**Contract Inspector Signature:**



Rick Hicks  
18.09.2022 15:08 EDT

By signing the Certification of Work, the said government representative does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline.

**Facility Manager Signature:**



Ken Augustin  
18.09.2022 15:08 EDT

**Date/Time:**

07.10.2022 12:59 EDT

## Appendix



Photo 1



Photo 2



Photo 3



Photo 4





Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12





Photo 13



Photo 14



Photo 15



Photo 16





Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24





Photo 25



Photo 26



Photo 27



Photo 28





Photo 29



Photo 30



Photo 31



Photo 32



Photo 33




Photo 34



Photo 35



Photo 36





Photo 37




Photo 38




Photo 39



Photo 40





Photo 41

[IMG\\_1076.mov](#)