

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY051 Date of Visit: 11/4/22

Contractor Personnel on Site:

1. Patrick Brown 3. _____
2. _____ 4. _____

Work Performed:


Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO#'S , 19416 , 19434 , 19435 , 19487 , 19520-19523 ,
2. 19694 , 19706 , 19717 , 19488
3. ASSET#'S , 10043 , 10066 , 10069 , 10044 , 10045 ,
4. 10067 , 10068 , 10037 , IL-, 36,37 , 190917-, 294 , 299 ,
5. 280-284 , 295 , 296

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: PATRICK BROWN Date: 11/4/22

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Noah Ingerson Date: 11/4/2022


Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
EMERGENCY EXIT SIGNS AND WALL PACKS

ACTIVITY AND BLDG #: **NY051 BLDG 1&2**

BLDG1&2	WO#	19522,	ASSET #	10067,
LOCATION/RM #:		19523,		10068,

MECHANIC
SIGNATURE: DATE: **11/4/22**START TIME: **10:30am**FINISH TIME: **11am**

CHECK POINT	CHECKPOINT DESCRIPTION	19717	190917	TAK C 295 E 296	NOTES/ ACTIONS	
					(IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)	
TO BE PERFORMED AT EACH INSPECTION SERVICE						
1	Inspect for structural defects, note needed repairs		✓			
2	Push test buttons and observe light operation. Note any units that do not operate properly.- Report issues and open a CM ticket		✓			
3	Clean exterior with dry cloth.		✓			
4	For Exit lights check for proper arrow direction.		✓			
5	Make and/or recommend any needed repairs.		✓			

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: