

SAUNDERS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: 7A087 Date of Visit: _____

Contractor Personnel on Site:

1. _____ 2. _____

Work Performed: Tested a 3/4" Watts RP2 and it passed

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 7268 Asset # 7228 PM # 1014

Service Calls - Service Call Number and Description

1. CSS# _____
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Boris Martinovich Date: 2-8-19

Signed: Boris Martinovich

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: 651 Wolff, James T. Date: 8 FEB 19

Signed: James T Wolff

E-Mail: James.t.wolff@corporate.com

The image shows a Watts RPZ backflow preventer mounted on a horizontal pipe. The device is dark-colored metal with four vertical test ports at the top. A yellow tag is hanging from the right side of the unit.

BACKFLOW PREVENTER TEST					
MAKE	<i>Watts RPZ</i>				
MODEL	<i>909 QT</i>				
SERIAL #	<i>477 234</i>				
SIZE	<i>3/4"</i>				
DATE	#1 CHECK	#2 CHECK	RELIEF PSI	PASSED	
<i>2-8-19</i>	<i>6.8</i>	<i>3.2</i>	<i>4.2</i>	<i>YES</i>	

SENTRY MECHANICAL, LLC.
 1015 SECO ROAD • MONROEVILLE, PA 15146
 (412) 380-0395 • (412) 380-0397

[illegible]

Watts RPZ

909 QT

477234

 $\frac{3}{4}$

SIZE

52

1015 SECO ROAD • MONROEVILLE, PA 15146

(412) 380-0395 • (412) 380-0397

PA087-02

Asset # 7228-Backflow-