

Date: 5/9/2025

Region: 4C

CSS No.: 2965913

FAC ID: WV009

Maximo WO No.: 17372

Asset #: NA

Priority: Urgent



Original Work Request:

Repair urinal, leaking from the flush valve.

Description of Repairs Needed:

Labor and material to a) Disconnect flush valve, b) remove urinal from wall, c) remove damaged gasket, d) replace gasket, e) reinstall urinal, f) reinstall flush valve, g) clean up and dispose of debris properly.

Labor:

	Labor Hrs	Labor Rate	Total
Technician (2 Techs)	16	\$ 135.00	\$ 2,160.00
			\$ -

Material List:

Material	Quantity	Cost	Total
	1	\$ 32.45	\$ 32.45
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 2,160.00	\$ 32.45	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,192.45	\$263.09	\$131.55	\$2,587.09

**CUSTOM CONSTRUCTION
CHRIS MOORE
103 SWEITZER RD.
ACME PA.15610
(724) 244-9438**

PROPOSAL

DATE: 5/5/25

SUBMIT TO:

JULIE PAPE
TIDE WATER

LOCATION

CLARKSBURG USARC
CLARKSBURG, WV.

WORK TO BE PERFORMED :

DISCONNECT FLUSH VALVE
REMOVE URINAL FROM WALL
REMOVE DAMAGED GASKET
REINSTALL URINAL
REINSTALL FLUSH VALVE
CLEAN UP AND DISPOSE OF DEBRIS PROPERLY

MATERIAL \$ 32.45
LABOR \$ 2160.00 (16 HRS @ \$135.00/HR.) TWO TECHS REQUIRED

ESTIMATE \$ 2192.45