

Date: 3/13/2025

Region: 4A

FEMS No.: 3071295

FAC ID: NY030

Maximo WO No.: 18310



Asset #: NA

Priority: Urgent

Original Work Request:

Perform annual backflow test and inspection for 2 each back flow devices located in the training building. Upon completion of the inspection please forward the inspection form to the local water authority for completion.

Description of Repairs Needed:

Labor and material to a.) perform (2) annual backflow inspections. Watts 2", Watt 1".

Labor	Labor Hrs	Labor Rate	Total
Technician	4	\$ 100.00	\$ 400.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$400.00	--	--	\$400.00

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selkirk Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 3/13/2025
FAC ID: NY030

FEMS #: 3071295
WO #: 18310

DESCRIPTION OF WORK			
Labor and material to a.) perform (2) annual backflow inspections. Watts 2", Watt 1".			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	4	\$100.00	\$400.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$400.00
	MATERIAL TOTAL		\$0.00
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$400.00

Accepted By: _____

Date: _____