

Date: 5/16/2025



Region: 4A

FEMS No.: 3114293

FAC ID: NY070

Maximo WO No.: 18772

Asset #: NA

Priority: Routine

Original Work Request:

Replace garbage disposal. Garbage disposal in OMS breakroom R.121, it has stopped working, smokes when trying to run.

Description of Repairs Needed:

Labor and material to a.) remove defective garbage disposal, b.) supply and install new garbage disposal in VMS break room, c.) test for proper operation, d.) clean area and properly dispose of all debris at job site.

Labor:	Labor Hrs	Labor Rate	Total
Service Technician	8	\$ 100.00	\$ 800.00
			\$ -

Material List:	Quantity	Cost	Total
Badger 500 1/2 hp	1	\$ 139.00	\$ 139.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 800.00	\$ 139.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$939.00	\$112.68	\$56.34	\$1,108.02

HUNOLD CONTRACTING INC.

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape

6625 Selmick Dr., Suite A

Elkridge, MD 21075

ESTIMATE**5/15/25**

Quantity	Description	Amount
1	FEMS 3114293, WO 18772, NY070 Webster, NY Replace garbage disposal VMS break room. Material: (\$139 -Badger 500 ½ hp) Labor: (8 hours @\$100/ hr.) =\$800	939.00
Sub total		939.00
Sales Tax		N/A
Total		939.00

Signature_____ **Date**_____**Signature**_____ **Date**_____