

Date: 6/9/2025

Region: 4A

FEMS No.: 3189934

FAC ID: NY126

Maximo WO No.: 19162

Asset #: NA

Priority: Urgent



**Original Work Request:**

Make repairs/replace OWS lid. The lid to the oil water separator was run over by a large piece of equipment and is now dented in and is now unable to be opened. The lid may need to be cut to remove it. The existing hinges are in good condition and can be reused.

**Description of Repairs Needed:**

Labor and material to a.) anchor a 4' x 4' x 1/2" steel plate to concrete over aluminum lid of OWS to prevent future damage. The plate will be removable for PM.

Labor:	Labor Hrs	Labor Rate	Total
Technician	12	\$ 100.00	\$ 1,200.00
			\$ -

Material List:	Quantity	Cost	Total
Steel plate and anchors, etc.	1	\$ 421.00	\$ 421.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 1,200.00	\$ 421.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,621.00	\$194.52	\$97.26	\$1,912.78

**HUNOLD CONTRACTING INC.**  
72 PENDERGAST ROAD  
PHOENIX, NY 13135  
Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape  
6625 Selmick Dr., Suite A  
Elkridge, MD 21075

**ESTIMATE**  
**6/2/25**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	FEMS 3189934, WO 19162, NY126 Chili, NY  Repair OWS lid as needed. Anchor 4' x 4'x ½" steel plate to concrete over aluminum lid.  Material: (\$421) Labor: (12 hours @ \$100/ hr.) = \$1200	<b>1621.00</b>
		<b>Sub total</b> <b>1621.00</b>
		<b>Sales Tax</b> <b>N/A</b>
		<b>Total</b> <b>1621.00</b>

**Signature** \_\_\_\_\_ Date \_\_\_\_\_

**Signature** \_\_\_\_\_ Date \_\_\_\_\_