

Date: 10/9/2025

Region: 4A

FEMS No.: 3265364

FAC ID: NY010

Maximo WO No.: 20295

Asset #: NA

Priority: Routine



Original Work Request:

Remove and replace drain covers in boiler room- basement. Two drain covers located in the boiler room need replacement. The 1st one is old and cracked in half, exposing the drain line underneath. The 2nd is located under the circulating pumps and has become old, rusty and starting to deteriorate.

Description of Repairs Needed:

Labor and material to a.) remove old broken drain covers, b.) supply and install (2) Grate drain covers 8in

Labor:	Labor Hrs	Labor Rate	Total
Service Technician	7	\$ 100.00	\$ 700.00
			\$ -

Material List:	Quantity	Cost	Total
Drain covers	2	\$ 37.00	\$ 74.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 700.00	\$ 74.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$774.00	\$92.88	\$46.44	\$913.32

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: Julie Pape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
10/9/25

Quantity	Description	Amount
1	FEMS 3265364, NY010 Amherst, NY WO 20295 Repair boiler room drain covers. Material: \$74 Labor: (7 hours @ \$100/ hr.) = \$700	774.00
		Sub total 774.00
		Sales Tax N/A
		Total 774.00

Signature _____ Date _____

Signature _____ Date _____