

Date:

1/20/2026



Region:

4A

FEMS No.:

340279

FAC ID:

NY065

Maximo WO No.:

20752

Asset #:

NA

Priority:

Routine

**Original Work Request:**

Lift master on overhead door in drill hall will not shut with mechanical control. The door can only be closed using the manual pulley. This has been worked on in a previous ticket and the lift master may need to be replaced with a new unit.

**Description of Repairs Needed:**

Labor and material to a.) Troubleshooting Liftmaster overhead door opener. Given the symptoms of the opener, I would suggest a general service call. Clean and lubricate as needed. Check electrical connections and photo eye alignment. Replacement does not seem necessary at this time.

**Labor:**

	Labor Hrs	Labor Rate	Total
Technician	8	\$ 100.00	\$ 800.00
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ 150.00	\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 800.00	\$ -	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$800.00	\$96.00	\$48.00	\$944.00

**HUNOLD CONTRACTING INC.**

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape

6625 Selmick Dr., Suite A

Elkridge, MD 21075

**ESTIMATE****12/26/25**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	FEMS 3402769, WO 20752, NY065 Tonowanda, NY  Troubleshoot and service overhead door opener that is not operating properly. Suggest general service items. Check wiring and connections, lubricate as needed and check photo eye alignment. Replacement does not seem necessary at this time.  Material: (Unknown at this time.) Labor: (8 hours @\$100/ hr.) =\$800	<b>800.00</b>
<b>Sub total</b>		<b>800.00</b>
<b>Sales Tax</b>		<b>N/A</b>
<b>Total</b>		<b>800.00</b>

Signature\_\_\_\_\_ Date\_\_\_\_\_

Signature\_\_\_\_\_ Date\_\_\_\_\_