

Date: 3/24/2026



Region: 4C

FEMS No.: 3402817

FAC ID: WV010

Maximo WO No.: 21465

Asset #: NA

Priority: Routine

Original Work Request:

Repair drain under ice machine in kitchen. Completely clogged.

Description of Repairs Needed:

Labor and material to a.) move ice machine, b.) snake out clogged drain, c.) run water through drain to confirm clog is removed, d.) clean up disturbed area, e.) place ice machine back in place.

Labor:	Labor Hrs	Labor Rate	Total
Technicians (2 Techs)	16	\$ 100.00	\$ 1,600.00
			\$ -

Material List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
Snake rental	1	\$ 200.00	\$ 200.00
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,600.00	\$ -	\$200.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,800.00	\$216.00	\$108.00	\$2,124.00



DBA TC3 Services  
 142 Terrace Manor  
 Fairmont, WV 26554

# Estimate

Date	Estimate #
3/24/2026	1175

Name / Address
Tidewater Inc Julie Pape 6625 Selnick Drive, Ste A Elkridge, MD 21075

Description	Hours	Rate	Total
WV010 Bridgeport Drain Clog FEMS: 3402817 WO: 21465  Problem: Clogged drain under ice machine.  Move ice machine. Snake out clogged drain. Run water through drain to confirm clog is removed. Clean up disturbed area. Place ice machine back in place.  Labor: (2) two employees Equipment: Snake rental  *Another quote will follow, if this does not fix the problem	16	100.00 200.00	1,600.00 200.00

Thank you for doing business with Tri-City Electric!		<b>Total</b>	\$1,800.00
Approval Signature:			
tcmelissa@gmail.com	Phone: 304-363-2843		