

Date: 3/30/2026



Region: 4A

FEMS No.: 3576745

FAC ID: NY070

Maximo WO No.: 21630

Asset #: NA

Priority: Routine

Original Work Request:

Remove damaged single arm barbed wire support and install two arm barbed wire support around MEP equipment compound. This issue was noted during the site PSI inspection.

Description of Repairs Needed:

Labor and material to a.) Remove and replace 365 LF of barbed wire with 6 strand 2-way hardware and wires, b.) clean up and properly dispose of all spent materials

Labor:	Labor Hrs	Labor Rate	Total
Technicians	24	\$ 110.00	\$ 2,640.00
			\$ -

Material List:	Quantity	Cost	Total
Barbed wire, 2-way 6 strand wire assy, bands for wire terminations, inserts for 3 strand assy, black paint)	1	\$ 917.00	\$ 917.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 2,640.00	\$ 917.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,557.00	\$426.84	\$213.42	\$4,197.26

HUNOLD CONTRACTING INC.

72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
3/26/26

Quantity	Description	Amount
1	FEMS 3576745, WO 21630, NY070 Webster, NY Remove and replace 365 Lf. of barbed wire with 6 strand 2-way hardware and wires. Material: \$917 (barbed wire, 2-way 6 strand wire assy., bands for wire terminations, inserts for 3 strand assy., paint) At this time I cannot find the new 2-way hardware in a black finish. So I'm assuming I will have to paint the new pieces. Labor and materials for that included. Opinion: The inserts are inexpensive installed at this time and that would be the next PSI deficiency. Labor: (24 hours @ \$110/ hr.) =\$2640	3557.00
Sub total		3557.00
Sales Tax		N/A
Total		3557.00

Signature _____ **Date** _____

Signature _____ **Date** _____