

Additional Funding Request

Site: WV046	WO#8137	CSS # 17350	Asset# NA
Description of Repairs	Air valve for oil recovery system leaking air. Please troubleshoot and repair.		
Diagnosis: Initial Work Order CSS# 17350	Air valve for oil recovery system leaking air. Please troubleshoot and repair.		
Explanation of Additional Costs for Repairs	Labor to diagnose issues with oil recovery system		
Additional Labor Cost to Perform Repairs	10.5 hours x \$121.41= \$1,274.80		
Additional Material Cost to Perform Repairs	\$200 (Consumables) + \$85.48= \$285.48		
Total Cost of Repair	\$1,560.28		

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV046

Date of Visit: 2/28/19

Contractor Personnel on Site:

1. Ray Chain
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. _____
2. _____
3. _____
4. _____

Other Recurring Services

1. _____
2. _____
3. _____
4. _____

Service Calls – Service Call Number and Description

1. 7586 Diagnose Part B washer
2. 7587 Diagnose Lube System issues
3. 7589 Diagnose AIR valve on Oil Recovery System

Description of Problem


Over and Above Repair Work – Order Number and Description of Work Completed

7587 Lube - BAY 2/3 Lenskit Hose BAY 6/7 Screen Broken. Yellow
BAY 6/7 worn smy Locked Bkt BAY 6/7 Blue worn smy
BAY 3/4 15/16 Blue Broken Screen (And) Blue Hose Lents
BAY 3/4 15/16 - Yellow Doesnt work
7587 Lube Pump Area - NEED 4 New O-Ring, All 4 regulation links
Oil Recovery - AIR valve Does not shut when tank is full - Spill Risk!
Parts washer - Rotation motor seized, Electronic Controls Burned up
7586

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Ray Chan Date: 2/28/19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Dwayne Felton WG08 Date: Feb 28, 2019

Signed: 

E-Mail: dwayne.a.felton4.civ@mail.mil

