



Repair leaking flush lever on ADA stall commode and repair cracked commode. Crack from in front of Johnny bolts on one side of base all the way around the back and forward of the Johnny bolt on the other side. Located in male latrine.

Initial Call:

- Replace leaking flush lever

Proposal to provide and perform the following:

- Remove ADA toilet
- Install new ADA Toilet

CMI Cost Estimate								
Funding Request								
PA011								
Repair leaking flush lever								
CSS #16878 - CMI # 7517								
Prepared By: J. Bayne								
02.15.19								
P3								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	8						\$ 784.00
1.2 Material					\$ -	\$ -	\$ -	\$ 115.59
Sub Total Repair Cost								\$ 899.59
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	2						\$ 196.00
2.2 Material truck stock								\$ 50.00
Grand Total								\$ 1,145.59