

## FILTER REPLACEMENT

**DATE:** 8/7/24

**FINISH TIME: 11AM**A photograph of two large, stainless steel commercial refrigerators standing on wooden pallets in a kitchen. The refrigerator on the right is taller and has two doors with large black handles. The one on the left is shorter and also has two doors with black handles. A doorway is visible in the background between the two units.

Both Refrigerator and Freezer has been replaced and needs installed. Also, both do not have filters.  
No Ice amachine at VA012.