

# SENTRY MECHANICAL

1724 Leechburg Road  
Pittsburgh, PA 15235  
Phone: 412-795-3040  
Fax: 412-795-3204  
Service Fax: 412-795-3206

24 Hour Service



## INVOICE

SOLD TO CMI Management, Inc  
c/o Bernard Koblinsky  
939 Freeport Road  
Natrona Heights, PA 15065

SHIP TO PA042 Greensburg Backflow  
900 Armory Drive  
Greensburg, PA 15601

ACCOUNT NO	PO NUMBER	SHIP VIA	JOB NUMBER	TERMS	INVOICE DATE	PAGE
CMIM001	19253		193119TP	Net 30	5/23/2019	1

RE: PA042 Greensburg  
CSS 19253  
WO8987

05/14/19:

Backflow test for device serial #18759 located in storage room. Device was missed on maintenance due to being located in a locked storage room.

ITEM NO	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENDED
PLUMBING SERVIC	1:0	05/14/19: Bo Martinovich	98.00	98.00

**TOTAL AMOUNT 98.00**

**Tammy Rubright**

---

**From:** Michele Dubois <michele.dubois@cmimgmt.com>  
**Sent:** Tuesday, May 14, 2019 1:20 PM  
**To:** Tammy Rubright  
**Cc:** Joe Bayne; Bernie Koblinsky  
**Subject:** New SC WO 8987, CSS 19253, PA042-01- BACKFLOW INSPECTION

Tammy,

I understand this is being performed today.

CSS 19253 has been issued for the annual inspection of the BF device at PA042. It's for the 2" main SN:18759

Thank you,

Michele DuBois  
Service Desk / 99th - Region 4  
5285 Shawnee Road Suite #510  
Alexandria, VA 22312  
703-738-5307

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA 042 Date of Visit: 5-14-19

Contractor Personnel on Site:

1. \_\_\_\_\_ 2. \_\_\_\_\_

Work Performed: *Tested 2" wats Backflow and it passed*

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# C# 18759 M# 919 Asset # N/A

**Service Calls** - Service Call Number and Description

1. CSS# \_\_\_\_\_
2. CSS# \_\_\_\_\_
3. CSS# \_\_\_\_\_

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Bryan Martynovich Date: 5-14-19

Signed: Bryan Martynovich


To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Randy Baker Date: \_\_\_\_\_

Signed: Randy Baker

E-Mail: \_\_\_\_\_



WATTS®

www.watts.com  
N. Andover, MA 01845

SER.  
NO.

18759



CSA  
UPC  
GS

654-A

919-LOT

Q11

## BACKFLOW PREVENTER TEST

MAPS  
SERV

MAKE WA  
MODEL 919  
SERIAL # 18759  
SIZE 2 "

**SENTRY MECHANICAL, LLC.**  
1015 SECO ROAD • MONROEVILLE, PA 15146  
(412) 380-0395 • (412) 380-0397

# Sentry Mechanical

1724 Leechburg Road  
Pittsburgh, PA 15235  
412-795-3040

# WORK ORDER

Date: 05-14-2019  
Work Order #: 157407  
Tech: Bojan Martinovich  
Job:  
Customer: CMI Management, Inc  
Phone: (703) 738-5303  
Address: 900 Armory Drive Greensburg, PA 15601  
Payment Type:  
Amount Paid: 0.00  
Check #: 0  
Request: PM1014 - PA042 Test backflow Serial #18759 located in the storage room off the drill hall. Please get pictures of device, tag and asset tag.

## Work Completed

Tested a 2" watts backflow and it passed

## Material

Inventory Item	Description	Quantity	Price	Amount
----------------	-------------	----------	-------	--------

## Labor

Labor Item	Description	Hours	Price	Amount
------------	-------------	-------	-------	--------

## Customer Signature

randy baker



## Tech Signature

Bojan Martinovich

