

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

**INSPECTION, TESTING, AND CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY030, NY070, NY126 Date of Visit: \_\_\_\_\_  
NY032, NY052

Contractor Personnel on Site:

1. _____	4. _____
2. _____	5. _____
3. _____	6. _____

**Work Performed:**

**Inspection, Testing, and Certification**

1. <u>NY030 WO 8891 Asset 6572 WO 8892 Asset 6574 WO 8893 Asset 6576</u>	<u>8883</u>
2. <u>WO 8894 Asset 6577 WO 8895 Asset 6656 NY052 WO 8892 Asset 6560 WO 8884 Asset 6561</u>	<u>xxxxxx</u>
3. <u>NY070 WO 8930 Asset 6588 WO 8931 Asset 6605</u>	
4. <u>NY126 WO 8852 Asset 6529 WO 8853 Asset 6530</u>	

NY030 WO 8891 Asset 6572 WO 8892 Asset 6574 WO 8893 Asset 6576 WO 8894 Asset 6577 WO 8895 Asset 6656

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Timothy R Houk Date: 07/09/2019

Signed: Timothy R Houk

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John F. Granata AFOS Date: 7/9/19

Signed: J. F. Granata

E-Mail: john.f.granata.ctr@mail.mil



## OneCIS Insurance Company

95 Oakwood Rd  
Lake Zurich, IL 60047  
(855) 593-5115  
[www.us.bureauveritas.com](http://www.us.bureauveritas.com)

BUREAU  
VERITAS

7/9/2019

44110-007210.00

TEC 3 Olaf A. Frederikesen USARC  
198 Cornwell St  
Penn Yan, NY 14527-1343

**RE: Jurisdictional Inspection:**  
TEC 3 Olaf A. Frederikesen USARC  
198 Cornwell St  
Penn Yan, NY 14527-1343

Thank you for the consideration I received during my visit on May 10, 2019 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the objects listed below to determine compliance with jurisdictional laws and regulations. I was accompanied by John Granata, Area Facility Operations Specialist @ 585-944-9099, during my visit.

The inspections were performed on behalf of Tidewater, Inc. (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
2018	Water Tube	92431	92431	None
2018	Water Tube	92270	92270	None

The following observations were noted during the inspection of this equipment: the boilers and the boiler room were in good working order.

As a result of these inspections 0 recommendations were suggested.

Based upon this visit, OneCIS Operating Certificates for each boiler are being created and forwarded to the client.

The next inspection is tentatively scheduled to be completed by 05/10/2020.

Please contact me by phone at 724-396-5433 or by e-mail at [joseph.klages@bureauveritas.com](mailto:joseph.klages@bureauveritas.com) if there are any questions and to clear any recommendations.

Sincerely,

**Joseph Klages**

Joseph Klages  
Jurisdictional Inspection Specialist

**DISTRIBUTION**

Cc:

Tidewater Inc.  
Adam Colopy  
3761 Attucks Dr  
Powell, OH 43065-6080  
[adam.colopy@tideh2o.net](mailto:adam.colopy@tideh2o.net)