

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

INSPECTION, TESTING, AND CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: _____ Date of Visit: _____

Contractor Personnel on Site:

- | | |
|----------|----------|
| 1. _____ | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Work Performed:

Inspection, Testing, and Certification

- | |
|----------|
| 1. _____ |
| 2. _____ |
| 3. _____ |
| 4. _____ |

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: _____ Date: _____

Signed: Timothy R Houk

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: Cynthia Croyle

E-Mail: _____



OneCIS Insurance Company

95 Oakwood Rd
Lake Zurich, IL 60047
(855) 593-5115
www.us.bureauveritas.com

WO 8905 Asset 6580
WO 8906 Asset 6597
WO 8907 Asset 6612
WO 8908 Asset 6620

7/2/2019

44110-007210.00

Pendel Caminiti USARC
950 Sharon New Castle Rd
Farrell, PA 16121-1265

RE: Jurisdictional Inspection:
Pendel Caminiti USARC
950 Sharon New Castle Rd
Farrell, PA 16121-1265

Thank you for the consideration I received during my visit on May 29, 2019 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the objects listed below to determine compliance with jurisdictional laws and regulations. I was accompanied by Cindy Coryloe AFOS, 412-477-7816, during my visit.

The inspections were performed on behalf of Tidewater, Inc. (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
2010	Water Tube	6580	6580	None
2010	Water Tube	6597	6597	None
2010	Water Tube	6612	6612	None
2010	Water Tube	6620	6620	None

The following observations were noted during the inspection of this equipment: the boilers and the boiler room were in good working order.

As a result of these inspections 0 recommendations were suggested.

Based upon this visit, OneCIS Operating Certificates for each boiler are being created and forwarded to the client.

The next inspection is tentatively scheduled to be completed by 05/29/2020.

Please contact me by phone at 724-396-5433 or by e-mail at joseph.klages@onecis.com if there are any questions and to clear any recommendations.

Sincerely,

Joseph Klages

Joseph Klages
Jurisdictional Inspection Speciaist

DISTRIBUTION

Cc:

Tidewater Inc.
Adam Colopy
3761 Attucks Dr
Powell, OH 43065-6080
adam.colopy@tideh2o.net