

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

**INSPECTION, TESTING, AND CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: \_\_\_\_\_ Date of Visit: \_\_\_\_\_

Contractor Personnel on Site:

1. _____	4. _____
2. _____	5. _____
3. _____	6. _____

**Work Performed:**

**Inspection, Testing, and Certification**

1. _____
2. _____
3. _____
4. _____

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: Timothy R. Houk

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: Cynthia Croyle

E-Mail: \_\_\_\_\_



## OneCIS Insurance Company

95 Oakwood Rd  
Lake Zurich, IL 60047  
(855) 593-5115  
[www.us.bureauveritas.com](http://www.us.bureauveritas.com)

WO 8937 Asset 6590  
WO 8938 Asset 6607

7/2/2019

44110-007210.00

Franklin USARC  
1545 Airport Rd  
Franklin, PA 16323-1940

**RE: Jurisdictional Inspection:**

Franklin USARC  
1545 Airport Rd  
Franklin, PA 16323-1940

Thank you for the consideration I received during my visit on May 29, 2019 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the objects listed below to determine compliance with jurisdictional laws and regulations. I was accompanied by Cindy Coryloe AFOS, 412-477-7816, during my visit.

The inspections were performed on behalf of Tidewater, Inc. (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
2008	Water Tube	312391	312391	None
2008	Water Tube	312392	312392	None

The following observations were noted during the inspection of this equipment: the boilers and the boiler room were in good working order.

As a result of these inspections 0 recommendations were suggested.

Based upon this visit, OneCIS Operating Certificates for each boiler are being created and forwarded to the client.

The next inspection is tentatively scheduled to be completed by 05/29/2020.

Please contact me by phone 724-396-5433 or by e-mail at [joseph.klages@onecis.com](mailto:joseph.klages@onecis.com) if there are any questions and to clear any recommendations.

Sincerely,

*Joseph Klages*

Joseph Klages  
Jurisdictional Inspection Specialist

#### DISTRIBUTION

Cc:

Tidewater Inc.  
Adam Colopy  
3761 Attucks Dr  
Powell, OH 43065-6080  
[adam.colopy@tideh2o.net](mailto:adam.colopy@tideh2o.net)