

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

INSPECTION, TESTING, AND CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: _____ Date of Visit: _____

Contractor Personnel on Site:

- | | |
|----------|----------|
| 1. _____ | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Work Performed:

Inspection, Testing, and Certification

- | |
|----------|
| 1. _____ |
| 2. _____ |
| 3. _____ |
| 4. _____ |

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: _____ Date: _____

Signed: Timothy R Houk

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: Cynthia Croyle

E-Mail: _____



OneCIS Insurance Company

95 Oakwood Rd
Lake Zurich, IL 60047
(855) 593-5115
www.us.bureauveritas.com

WO 8882 Asset 6559

7/2/2019

44110-007210.00

ECS/AMSA #103 (G)
6467 Mike Wood Blvd
Conneaut Lake, PA 16316-6661

RE: Jurisdictional Inspection:
ECS/AMSA #103 (G)
6467 Mike Wood Blvd
Conneaut Lake, PA 16316-6661

Thank you for the consideration I received during my visit on May 29, 2019 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the object listed below to determine compliance with jurisdictional laws and regulations. I was accompanied by Cindy Coryloe AFOS, 412-477-7816, during my visit.

The inspection was performed on behalf of Tidewater, Inc. (US Army Reserve Offices).

The following object was inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
2012	Cast Iron	6559	6559	None

The following observations were noted during the inspection of this equipment: the boiler and the boiler room were in good working order.

As a result of this inspection 0 recommendations were suggested.

Based upon this visit, a OneCIS Operating Certificate was created and forwarded to the client.

The next inspection is tentatively scheduled to be completed by 05/29/2020.

Please contact me by phone at 724-396-5433 or by e-mail at joseph.klages@onecis.com if there are any questions and to clear any recommendations.

This document is advisory in nature. Reports or certificates provided in connection with any state-required boiler or pressure vessel inspection do not mean that all hazards or conditions were controlled at the time of the inspection. No liability is assumed by the information contained in this document.

Sincerely,

Joseph Klages

Joseph Klages
Jurisdictional Inspection Specialist

DISTRIBUTION

Cc:

Tidewater Inc.
Adam Colopy
3761 Attucks Dr
Powell, OH 43065-6080
adam.colopy@tideh2o.net