

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY013 Date of Visit: 2/16/22

Contractor Personnel on Site:

- | | |
|-------------------------|----------|
| 1. <u>PATRICK BROWN</u> | 3. _____ |
| 2. _____ | 4. _____ |

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO#'S , 15945 , 15946 , 16119-16125 , 16238 , 16252 , 16267 ,
2. 15968 , 16126-16128
3. ASSET#S , 9218-9220 , 9222 , 9240 , 9241 , 9243 , 9244 , 9245 ,
4. 9254 , 9261 , 9262 , 9263 , 190917, 131 , 102 , 103 , 132 , 119 , 124 ,
5. 125 , 126

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Patrick Brown Date: 2/16/22

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: MR MCCARTHY Date: 2/16/22

Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
ISOLATION VALVE

SITE AND BLDG #: NY013 BLDG1





**MECHANIC
SIGNATURE:** 

DATE: 2/16/22

LOCATION/RM #: 119 **WO#** 16252 **ASSET #** 190917-103

START TIME: 12:50pm

FINISH TIME: 1pm

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Inspect valve for damage and/or leaks.			no damage or leaks found
2	Exercise valve (at least 2 times per year) to ensure proper function. If valve does not function properly and/or leaks, open CM ticket for repair. Note the location of the valve.			valves have been worked

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed discription of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: