




PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
ISOLATION VALVE

SITE AND BLDG #: NY067 BLDG1
 boiler room
LOCATION/RM #: **WO#** 21021 **ASSET #** 190917-430

MECHANIC SIGNATURE:  **DATE:** 2/7/23
START TIME: 11:30am **FINISH TIME:** 11:45am

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Inspect valve for damage and/or leaks.			
2	Exercise valve (at least 2 times per year) to ensure proper function. If valve does not function properly and/or leaks, open CM ticket for repair. Note the location of the valve.			

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed discription of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: