

**CERTIFICATION OF WORK  
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: \_\_\_\_\_ Date of Visit: 11/6/19

Contractor Personnel on Site:

1. _____	3. _____
2. _____	4. _____

**Work Performed:**

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)


1. \_\_\_\_\_
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Johnny W Brown Date: 11/6/19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Roderick Daniels Date: 11/6/19

Signed: 

E-Mail: \_\_\_\_\_

Wednesday, November 6, 2019 7:30 PM EST

Tidewater, INC  
 MD-003  
 5515 Liberty Heights Ave  
 Baltimore MD 21207-6999  
 (410) 540-8700

Report Number: 275073  
 Recorded By: Paul Giammanco  
 (301) 721-2663  
 pgiammanco@bondwater.com  
 On-Site Time: 11:00 AM EST to 12:15 PM EST

## 5515 Liberty Heights Ave - HOT LOOP

Test	Hot Loop			
Conductivity (as mmhos)	400 3500 max			
pH	8.0 8.5 - 10			
Molybdate (ppm as Mo)	0 80 min			

Hot loop

Online 

Performed start up service visit. Performed all tests for hot water loop. No treatment was detected so I added molybdate until reading was within range.