

## OVER AND ABOVE FUNDING

**Region:** 5

**Location:** MD013

**CSS #** 30527

**Maximo Work Order No.:** 14179

**Asset #:** NA

**Date Issued:** 05/13/2021

**Original Description:** Chiller #1 Compressor needs replaced

**Repairs Needed:**

S&S hereby proposes to complete the following:

S&S will reclaim any refrigerant and save for new install, will remove and dispose of the old compressor and install a new Carlyle compressor and liquid line drier on Carrier Chiller #1.

S&S will then add 50lbs of R22 refrigerant and complete a system check to ensure Chiller is now working properly.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Parts ( See detail attached Quote)	--	--	\$4,588.49	--	\$4,588.49
--	NA	Optional Ext Warranty from 24 months to 60 months	--	--	\$570.00	--	\$570.00
--	NA	SS Labor	26	\$100.00	--	--	\$2,600.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Warranty	Total Cost	CE Factor	Total Estimate
26	\$2,600.00	\$4,588.49	\$570.00	\$7,758.49	106%	<b>\$8,224.00</b>