

OVER AND ABOVE FUNDING

Region: 5

Location: MD013

CSS # 30527

Maximo Work Order No.: 14179

Asset #: NA

Date Issued: 05/13/2021

Original Description: Chiller #1 Compressor needs replaced

Repairs Needed:

S&S hereby proposes to complete the following:

S&S will reclaim any refrigerant and save for new install, will remove and dispose of the old compressor and install a new Carlyle compressor and liquid line drier on Carrier Chiller #1.

S&S will then add 50lbs of R22 refrigerant and complete a system check to ensure Chiller is now working properly.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Parts (See detail attached Quote)	--	--	\$4,588.49	--	\$4,588.49
--	NA	SS Labor	26	\$100.00	--	--	\$2,600.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
26	\$2,600.00	\$4,588.49	NA	\$7,188.49	106%	\$7,619.80