

Additional Funding Request

Submitted: 06/07/2021

MD013 – Men's Urinal	CSS # 30879 WO#14371								
Description of Repairs	Men's room urinal was drawing very slow and the flush valve was leaking and flushing long and would not adjust. Unclogged the fixture by vacuuming the trap out to clear debris and then using liquid lightning. Test several times and now draining properly. The flush valve I replaced with a new sloan valve it now flushes and drains properly								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	The men's room urinal is not flushing well.								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials \$228.01</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts Detail in Quote</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$228.01</td> <td style="text-align: left; padding: 2px;">\$228.01</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts Detail in Quote	1	\$228.01	\$228.01
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Parts Detail in Quote	1	\$228.01	\$228.01						
Additional Labor Cost to Perform Repairs	<p>Labor: \$275.00 2.75 hrs each/Rate \$100 per hour = \$275.00</p>								
Total Cost of Repair	\$503.01								