

Additional Funding Request

Submitted: 11/6/2018

MD013 - check operation of heating system	CSS #16141 WO#6454
Description of Repairs	<p>S&S hereby proposes to check proper operation of the heating system in the following areas:</p> <ul style="list-style-type: none"> • 216 • 215 • 214 • 213 • 212 • 210 • 209 • 208 • 205 • 204 • 125 • 123 • 121 • 120 • 119 • 118 • 113 #3 • 108 #01 and #02 • Cube city #1 and #05
Diagnosis: Initial Work Order	Investigate the operation of the heating system of areas above
Explanation of Additional Costs for Repairs	N/A
Investigative Diagnosis from SC	N/A
Additional Material Cost to Perform Repairs	Materials = N/A
Additional Labor Cost to Perform Repairs	1 HVAC Technician/ 10hrs/ Rate \$100.00 = \$1,000.00
Total	\$1,000.00