

Region: 5

Location: MD016

CSS # 973

Maximo Work Order No.: 17824

Asset #: NA

Date Issued: 06/29/22

Original Description: MD016 was broken into AGAIN-Cleanup

Repairs Needed:

Patrick Donovan on site to try to locate the water shut off to stop the flooding.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Parts See attached invoice			296.13		296.13
--	NA	S&S Labor	24	\$80.00	--	--	\$1,920.00
--	NA	CMI Labor	8	\$80.00	--	--	\$640.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Lift	Total Cost	CE Factor	Total Estimate
32	\$2,560.00	\$296.13		\$2,856.13	106%	\$3,027.50