

**Additional Funding Request
Over & Above (IDIQ)**

Submitted: 4/8/2019

MD016 – broken pipe	CSS #18544 WO #8451
Description of Repairs	Follow up of emergency service call of 2 foot of water in mechanical room.
Diagnosis: Initial Work Order	<p>S&S Mechanical is providing this quote to CMI to replace the parts for the boiler and water heater that have been damaged due to motor room leak.</p> <ul style="list-style-type: none"> ❖ S&S will provide blower motor, burner control, and flame card for boiler. ❖ S&S will provide system checks of boiler after installation of new parts. ❖ S&S will provide and install new gas valve for water heater. ❖ S&S will provide system check of water heater once parts are installed.
Diagnostic Fee	Diagnostic Total: NA
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	<p>Labor: \$900.00</p> <p>1 HVAC Technician /9 hours/ Rate \$100.00 per hour = \$900.00</p>
Additional Material Cost to Perform Repairs	<p>Materials: \$2, 352.03</p> <p>Blower Motor/VEM31111/\$515.11 Shipping: \$50.00 Gas Valve/70-1551/\$462.00 Shipping: \$25.00 Burner Control/RM7895A1014/\$805.69 Shipping: \$25.00 Ultraviolet card/R7849A1023/\$227.94 Tax: \$241.29</p>
Total Cost of Repair	\$3,252.03