

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD019 B-1 Date of Visit: 11/15/19

Contractor Personnel on Site:

1. <u>Paul Giannamico</u>	4. _____
2. <u>John Brown</u>	5. _____
3. _____	6. _____

**Service Call Number**

CSS# \_\_\_\_\_ WO# \_\_\_\_\_

**Description of Repairs**

water treatment for systems

WO 11205 ASSET 190918-197

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Paul Giannamico Date: 11/15/19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: 1st SGT Nathan Maze Date: 11/15/19

Signed: 

E-Mail: \_\_\_\_\_

Friday, November 15, 2019 5:41 PM EST

Tidewater, INC  
 MD-019  
 12100 Greenspring Ave  
 Owings Mills MD 21117-1610  
 (410) 540-8700

Report Number: 275341  
 Recorded By: Paul Giammanco  
 (301) 721-2663  
 pgiammanco@bondwater.com  
 On-Site Time: 9:45 AM EST to 11:00 AM EST

## MD-019 - Closed Loops

Test	Hot Loop	Chilled Glycol Loop		
Conductivity (as mmhos)	180 3500 max	2600 3500 max		
pH	8 8 - 10.5	8 8 - 10		
Molybdate (ppm as Mo)	0 50 - 200	0 50 - 200		

### Opening Comment

Performed monthly scheduled service visit.

#### Hot Water Loop

Online 

Performed all tests for hot loop. No treatment detected. Added molybdate to pot feeder until desired reading was acquired.

#### Chill Water Glycol Loop

Online 

Performed all tests for chilled glycol loop. No treatment detected. Added molybdate to pot feeder until desired reading was acquired.