

### Additional Funding Request

Submitted: 3/25/2019

<b>MD020 – Shower handle</b>	<b>CSS #17971 WO#7994</b>
Description of Repairs	2nd floor men's room - there is a showerhead with a slow leak
Diagnosis: Initial Work Order	<p>S&amp;S proposes to furnish the labor and material necessary for the completion of the following:</p> <ul style="list-style-type: none"> <li>- S&amp;S will remove the broken shower handle and replace with new compatible handle.</li> <li>- Work will take place during normal business hours.</li> </ul>
Explanation of Additional Costs for Repairs	Additional part needed, shower handle
Investigative Diagnosis fee from SC	<b>Diagnostic Total: \$450.00 (already billed)</b>
Additional Material Cost to Perform Repairs	<p><b>Material: \$50.76</b></p> <p>Shower handle/ PF7610GCP/=\$45.31 Tax: \$5.45</p>
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$250.00</b></p> <p>1 Plumber /2.5 hours/ Rate \$100.00 per hour = \$250.00</p>
<b>Total Cost</b>	<b>\$300.76</b>