

### Additional Funding Request

Submitted: 8/29/2019

<b>MD020 – water leak</b>	<b>CSS #20722 WO#10588</b>
Description of Repairs	Water leak, see pics uploaded, investigate the cause and estimate the repair.
Diagnosis: Initial Work Order	S&S investigated outside perimeter of the building. Located area of the leak and where the street water shut off valve is located. Need to pump out water and dig down to pipe. Once pipe is dug up, we can figure out what size the pipe is and what material is needed to make the repair.
Explanation of Additional Costs for Repairs	
Investigative Diagnosis fee from SC	<b>Diagnostic Total: \$250.00</b>
Additional Material Cost to Perform Repairs	<p><b>Material: Undetermined - We are requesting NTE\$2500, so when the issue is discovered we can make repairs on the spot.</b></p> <p>Invoices and hours will be tracked. Pricing will be adjusted per hours used.</p>
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$1,200.00</b></p> <p>2 HVAC Technician/12 Hours/\$100.00 rate= \$1,200.00</p>
<b>Total Cost</b>	<b>\$1,450.00 + \$1,050.00 = NTE \$2,500.00</b>