

## Additional Funding Request

<b>MD021 Winter change over</b>	<b>CSS #16108 WO#6425 Asset # N/A</b>
Description of Repairs	Winter change over
Diagnosis: Initial Work Order CSS# <b>16108</b>	Winterize chiller barrel
Explanation of Additional Costs for Repairs	Isolate and drain chiller for winter .No Glycol in system
Additional Labor Cost to Perform Repairs	\$250.00= Labor 2.5 hours @ \$100.00 per hour = \$250.00
Additional Material Cost to Perform Repairs	
<b>Total cost</b>	<b>\$250.00</b>



# S&S MECHANICAL

4845 South Crain Highway  
Upper Marlboro, Maryland 20772

301-574-1555

## Invoice

Date	Invoice #
10/22/2018	58400

Bill To
CMI Management, Inc. Richard Hicks 5285 Shawnee Road Suite #510 Alexandria, VA 22312

Service Address
MAUS-WARFIELD USARC - MD021 1850 Baltimore Road Rockville, MD 20851

Work Order No.	Terms
6425	Net 30

Item	Description	Qty	Rate	Amount
HVAC Labor	Winterization of Chiller: Isolated chiller and drained water. Turned breakers to chiller off. Went to EMS and checked status. Switched manual switch on back of wall to winter. Work complete.	1.5	100.00	150.00
HVAC Travel	- Anti-FREEZE in Chiller Barrel.  W# 6425 CSS# 16108 MD021 Chiller Shut down & Winterize 2 STK BOTTLES	1	100.00	100.00
**Tax is included in total invoice amount**				

Make all checks payable to S&S Mechanical. Overdue accounts are subject to a service charge of 1% per month. Thank you for your business.

**Payments/Credits** \$0.00

**Balance Due**

\$250.00

info@sandsmidatlantic.com

www.sandsmidatlantic.com