

Additional Funding Request

Submitted: 1/13/21

MD021-Splash Guard on Kitchen Prep Table	CSS # 28449 WO# 13462												
Description of Repairs	S&S proposes to replace the sanitary splash guard on the kitchen prep table. S&S proposes to install, cut and ease edges 3/8" plexiglass on the kitchen prep table.												
Original SC Investigative Diagnosis	\$ NA												
Diagnosis: Initial Work Order	Replace Splash Guard on Kitchen Prep Table												
Explanation of Additional Costs for Repairs	N/A												
Additional Material Cost to Perform Repairs	<p>Materials: \$654.60</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>3/8" Polycarbonate Sheet</td><td>1</td><td>\$615.60</td><td>\$615.60</td></tr> <tr> <td>Misc</td><td>1</td><td>\$39.00</td><td>\$39.00</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	3/8" Polycarbonate Sheet	1	\$615.60	\$615.60	Misc	1	\$39.00	\$39.00
ITEM	QUANTITY	UNIT PRICE	TOTAL										
3/8" Polycarbonate Sheet	1	\$615.60	\$615.60										
Misc	1	\$39.00	\$39.00										
Additional Labor Cost to Perform Repairs	<p>Labor: \$720.00 Plumber Labor Tech 9 hours/Rate \$80.00 per hour = \$720.00</p>												
Total Cost of Repair	\$1,374.60												