

OVER AND ABOVE FUNDING

Region: 5

Location: MD021

CSS # 32923

Maximo Work Order No.: 15138

Asset #: 1661

Date Issued: 06/29/2020

Original Description: Replace #2 boiler circulation pump . Asset# 1661

Repairs Needed:

S&S proposes to remove and replace the boiler circulation pump asset# 1661 on boiler 2. S&S will then complete a system check to ensure everything is working properly. NEEDS DONE BEFORE CERTIFICATION 10/27

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	ARMFLO E33 2/5HP 3300/1/60 and shipping	--	--	\$1,689.66	--	\$1,689.66
--	NA	SS Labor	12	\$100.00	--	--	\$1,200.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
12	\$1,200.00	\$1,689.66	NA	\$2,889.66	100%	\$2,889.66

