

Additional Funding Request

Submitted: 02/10/2022

MD021-Safety Lights	CSS #3444 WO#16429															
Description of Repairs	S&S proposes to replace (4) safety lights in the training building.															
Original SC Investigative Diagnosis	\$100.00															
Diagnosis: Initial Work Order	Replace bad safety lights (4) each in Training Building															
Explanation of Additional Costs for Repairs	N/A															
Additional Material Cost to Perform Repairs	Materials: \$192.04 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Bulbs</td><td style="text-align: left; padding: 2px;">4</td><td style="text-align: left; padding: 2px;">\$35.51</td><td style="text-align: left; padding: 2px;">\$142.04</td></tr> <tr> <td style="text-align: left; padding: 2px;">Shipping</td><td style="text-align: left; padding: 2px;">1</td><td style="text-align: left; padding: 2px;">\$50.00</td><td style="text-align: left; padding: 2px;">\$50.00</td></tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Bulbs	4	\$35.51	\$142.04	Shipping	1	\$50.00	\$50.00
ITEM	QUANTITY	UNIT PRICE	TOTAL													
Bulbs	4	\$35.51	\$142.04													
Shipping	1	\$50.00	\$50.00													
Additional Labor Cost to Perform Repairs	Labor: \$1000.00 10 hours each/Electrical Rate \$100.00 per hour = \$1,000.00															
Total Cost of Repair	\$1,292.04															