

## Additional Funding Request

Submitted: **2/16/2022**

<b>MD021-Boilers 1 and 2 low water cutoff valve</b>	<b>CSS #34478 WO#16435</b>								
Description of Repairs	S&S proposes to remove and replace the low water cutoff on Well McLain Boilers 1 & 2. S&S will then complete a system check to ensure everything is running properly								
Original SC Investigative Diagnosis	<b>\$300</b>								
Diagnosis: Initial Work Order	#1 and #2 boiler in alarm, both units alarms are Low Water Cutoff Open								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$878.84</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th><th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th><th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th><th style="text-align: left; padding: 2px;"><b>TOTAL</b></th></tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"><b>Parts/Shipping see detail in Quote</b></td><td style="text-align: center; padding: 2px;"><b>1</b></td><td style="text-align: center; padding: 2px;"><b>\$878.84</b></td><td style="text-align: center; padding: 2px;"><b>\$878.84</b></td></tr> </tbody> </table>	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	<b>Parts/Shipping see detail in Quote</b>	<b>1</b>	<b>\$878.84</b>	<b>\$878.84</b>
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>						
<b>Parts/Shipping see detail in Quote</b>	<b>1</b>	<b>\$878.84</b>	<b>\$878.84</b>						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$900.00</b> 9 hours each/HVAC Rate \$100.00 per hour = \$900.00</p>								
<b>Total Cost of Repair</b>	<b>\$2,078.84</b>								