

Additional Funding Request

Submitted: 10/18/19

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|--|----------|------------|----------|------|----------|------------|-------|------------------------------|------|----------|----------|----------------------------------|------|---------|----------|----------------------------------|------|---------|---------|-------------------------|------|--------|--------|----------|------|---------|---------|-----|--|--|--------|----------------------|--|--|----------|
| MD021 – aluminum jacket | CSS #21254 WO #10634 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Description of Repairs | Quote to have an aluminum jacket installed around the armor flex to protect it from any damage. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Diagnosis: Initial Work Order | S&S will install a new aluminum jacket around the suction line armor flex by the OMS shop. S&S will them do a system check to ensure everything is protected from any further damages. This work will take place during business hours. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Diagnostic Fee | Diagnostic Total: \$350.73 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Additional Labor Cost to Perform Repairs | <table><tr><td>ITEM</td><td>QUANTITY</td><td>UNIT PRICE</td><td>TOTAL</td></tr><tr><td>HVAC Labor Rate</td><td>5</td><td>\$100/hr</td><td>\$500.00</td></tr><tr><td>Total Labor</td><td></td><td></td><td>\$500.00</td></tr></table> | | | | ITEM | QUANTITY | UNIT PRICE | TOTAL | HVAC Labor Rate | 5 | \$100/hr | \$500.00 | Total Labor | | | \$500.00 | | | | | | | | | | | | | | | | | | | | |
| | ITEM | QUANTITY | UNIT PRICE | TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | HVAC Labor Rate | 5 | \$100/hr | \$500.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Total Labor | | | \$500.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Additional Material Cost to Perform Repairs | <table><tr><td>ITEM</td><td>QUANTITY</td><td>UNIT PRICE</td><td>TOTAL</td></tr><tr><td>Insulated Pipe Jacket/19NF04</td><td>1.00</td><td>\$246.13</td><td>\$246.13</td></tr><tr><td>Aluminum Pipe Fitting 45/ 19NF09</td><td>1.00</td><td>\$21.18</td><td>\$21.18</td></tr><tr><td>Aluminum Pipe Fitting 90/ 19NF22</td><td>3.00</td><td>\$16.86</td><td>\$50.58</td></tr><tr><td>Aluminum Straps/ SHU 37</td><td>1.00</td><td>\$7.21</td><td>\$7.21</td></tr><tr><td>Shipping</td><td>1.00</td><td>\$50.00</td><td>\$50.00</td></tr><tr><td>Tax</td><td></td><td></td><td>\$0.00</td></tr><tr><td>Total Cost Materials</td><td></td><td></td><td>\$375.10</td></tr></table> | | | | ITEM | QUANTITY | UNIT PRICE | TOTAL | Insulated Pipe Jacket/19NF04 | 1.00 | \$246.13 | \$246.13 | Aluminum Pipe Fitting 45/ 19NF09 | 1.00 | \$21.18 | \$21.18 | Aluminum Pipe Fitting 90/ 19NF22 | 3.00 | \$16.86 | \$50.58 | Aluminum Straps/ SHU 37 | 1.00 | \$7.21 | \$7.21 | Shipping | 1.00 | \$50.00 | \$50.00 | Tax | | | \$0.00 | Total Cost Materials | | | \$375.10 |
| | ITEM | QUANTITY | UNIT PRICE | TOTAL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Insulated Pipe Jacket/19NF04 | 1.00 | \$246.13 | \$246.13 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Aluminum Pipe Fitting 45/ 19NF09 | 1.00 | \$21.18 | \$21.18 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Aluminum Pipe Fitting 90/ 19NF22 | 3.00 | \$16.86 | \$50.58 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Aluminum Straps/ SHU 37 | 1.00 | \$7.21 | \$7.21 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Shipping | 1.00 | \$50.00 | \$50.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Tax | | | \$0.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Total Cost Materials | | | \$375.10 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Total Cost of Repair | \$1,225.83 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |