

### Over and Above Estimate

**Region:** 5

**Location:** MD021

**CSS #:** 22137

**Maximo Work Order No.:** 11266

**Date Issued:** 10/31/19

**Original Description:** Paint walls that had wallpaper removed, in Female restroom on first floor 125.

**S & S proposes to remove the existing glue from the previous wallpaper and replace the missing drywall. S & S will then primer and paint the woman's restroom on the first floor, room 125.**

#### Non Pre-Priced Estimate:

Quantity	Unit Price	Description	Labor Hours	Labor Rate/Hr.	Tax/Ship	Materials	Equipment	Total
1	N/A	See quote attached for materials detail				\$193.76		\$193.76
1	\$100.00	Diagnostic Labor Fee/S&S						\$100.00
N/A	N/A	General Maintenance Labor Rate	36	\$75.00				\$2,700.00
N/A	N/A	Tax			\$4.46			\$4.46

*Note: RS Means (Pre-Priced) not used in compiling this estimate.*

*Note: Subcontractor quote attached.*

#### Estimate Summary:

Labor Hours	Labor Cost	Material Cost		Total Cost	CE Factor	Total Estimate
36	\$2,800.00	\$93.76		\$2,893.36	100%	\$2,893.36