

## **Additional Funding Request**

Submitted: 10/15/20

<b>MD021 – Secure windows</b>	<b>CSS #PENDING WO# 12860</b>																
Description of Repairs	Secure windows in building - Meet with Ken to determine windows to secure.																
Original SC Investigative Diagnosis	N/A																
Diagnosis: Initial Work Order	S&S proposes to provide the necessary labor to secure approx 29 windows throughout the building in rooms 102A &B, 103, 104, 105, 107, 108, 109, 110, 113 & 130. S&S will furnish and install (2) aluminum roton surface mounted hinges on the lower wing double doors. S&S will remove the door in room 129 and store the door onsite.																
Explanation of Additional Costs for Repairs	N/A																
Additional Material Cost to Perform Repairs	<p><b>Materials: \$334.16</b></p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Materials (see attached detail)</td><td>1</td><td>\$284.16</td><td>\$284.16</td></tr> <tr> <td>Shipping</td><td>1</td><td>\$50.00</td><td>\$50.00</td></tr> <tr> <td>Total</td><td></td><td></td><td>\$334.16</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Materials (see attached detail)	1	\$284.16	\$284.16	Shipping	1	\$50.00	\$50.00	Total			\$334.16
ITEM	QUANTITY	UNIT PRICE	TOTAL														
Materials (see attached detail)	1	\$284.16	\$284.16														
Shipping	1	\$50.00	\$50.00														
Total			\$334.16														
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$1,600.00</b>            General Maintenance Labor Tech/20 hours/Rate \$80.00 per hour            = \$1,600.00</p>																
<b>Total Cost of Repair</b>	<b>\$1,934.16</b>																