



1-877-RPZ-TEST

Backflow Prevention Assembly Test Report

Property Name:	US Army Corps Reserve Bases
Street Address:	720 E. Ordinance Rd., Curtis Bay, MD, 21226
Onsite Contact:	
Onsite Phone:	
Contact Email:	
Assembly Status	<input type="radio"/> New Installation <input checked="" type="radio"/> Existing <input type="radio"/> Rebuilt <input type="radio"/> Replacement
Location:	Bldg 1 md024
Service::	domestic main line
Make::	Wilkins
Model:	975XL
Serial Number:	910054
Size:	1-1/2"
Type::	RPZA
Asse #:	1013

INITIAL TEST: ☒ Pass ☐ Fail

REPAIR FINAL TEST: ☐ Pass ☐ Fail

INITIAL TEST DATE: 2/5/2019

Final TEST DATE:

Shutoff #2 Close Tight: ☒ Y ☐ N

SHUTOFF #2 CLOSE TIGHT:

CV 1 Close Tight: ☒ Y ☐ N 10 PSID

CHECK #1 CLOSE TIGHT: ☐ Y ☐ N

CV 2 Close Tight: ☒ Y ☐ N 2.6 PSID

CHECK #2 CLOSE TIGHT: ☐ Y ☐ N

RPZ Relief Open: 2.0 PSID

RPZ RELIEF OPEN PSID:

PVB Open: PSID

PVB OPEN PSID:

Line Pressure: 130 PSI

Air Gap OK: ☒ Y ☐ N

Comments

Tester License #: MD 12654

Gauge: Mid-West 845-5

Tester Name: Brian Douglass

Serial Number: 10172721

Signature: Brian Douglass

Last Calibration: 10/31/2018



1-877-RPZ-TEST

Backflow Prevention Assembly Test Report

Property Name:	US Army Corps Reserve Bases
Street Address:	700 E. Ordinance Rd., Curtis Bay, MD, 21226
Onsite Contact:	
Onsite Phone:	
Contact Email:	
Assembly Status	<input type="radio"/> New Installation <input checked="" type="radio"/> Existing <input type="radio"/> Rebuilt <input type="radio"/> Replacement
Location:	Md024
Service::	domestic main line
Make::	Watts
Model:	007M2QT
Serial Number:	A01772
Size:	1-1/2"
Type::	DCVA
Asse #:	1015

INITIAL TEST: ☒ Pass ☐ Fail

REPAIR FINAL TEST: ☐ Pass ☐ Fail

INITIAL TEST DATE: 2/5/2019

Final TEST DATE:

Shutoff #2 Close Tight: ☒ Y ☐ N

SHUTOFF #2 CLOSE TIGHT:

CV 1 Close Tight: ☒ Y ☐ N 1.8 PSID

CHECK #1 CLOSE TIGHT: ☐ Y ☐ N

CV 2 Close Tight: ☒ Y ☐ N 1.8 PSID

CHECK #2 CLOSE TIGHT: ☐ Y ☐ N

RPZ Relief Open: PSID

RPZ RELIEF OPEN PSID:

PVB Open: PSID

PVB OPEN PSID:

Line Pressure: 120 PSI

Air Gap OK: ☐ Y ☐ N

Comments

Tester License #: MD 12654

Gauge: Mid-West 845-5

Tester Name: Brian Douglass

Serial Number: 10172721

Signature: Brian Douglass

Last Calibration: 10/31/2018



1-877-RPZ-TEST

Backflow Prevention Assembly Test Report

Property Name:	US Army Corps Reserve Bases
Street Address:	700 E. Ordinance Rd., Curtis Bay, MD, 21226
Onsite Contact:	
Onsite Phone:	
Contact Email:	
Assembly Status	<input type="radio"/> New Installation <input checked="" type="radio"/> Existing <input type="radio"/> Rebuilt <input type="radio"/> Replacement
Location:	Md024
Service::	Domestic Supply
Make::	Wilkins
Model:	975XL
Serial Number:	910040
Size:	1-1/2"
Type::	RPZA
Asse #:	1013

INITIAL TEST: ☒ Pass ☐ Fail

REPAIR FINAL TEST: ☐ Pass ☐ Fail

INITIAL TEST DATE: 2/5/2019

Final TEST DATE:

Shutoff #2 Close Tight: ☒ Y ☐ N

SHUTOFF #2 CLOSE TIGHT:

CV 1 Close Tight: ☒ Y ☐ N 9.0 PSID

CHECK #1 CLOSE TIGHT: ☐ Y ☐ N

CV 2 Close Tight: ☒ Y ☐ N 2.2 PSID

CHECK #2 CLOSE TIGHT: ☐ Y ☐ N

RPZ Relief Open: 2.6 PSID

RPZ RELIEF OPEN PSID:

PVB Open: PSID

PVB OPEN PSID:

Line Pressure: 130 PSI

Air Gap OK: ☒ Y ☐ N

Comments

Tester License #: MD 12654

Gauge: Mid-West 845-5

Tester Name: Brian Douglass

Serial Number: 10172721

Signature: Brian Douglass

Last Calibration: 10/31/2018



1-877-RPZ-TEST

Backflow Prevention Assembly Test Report

Property Name:	US Army Corps Reserve Bases
Street Address:	700 E. Ordinance Rd., Curtis Bay, MD, 21226
Onsite Contact:	
Onsite Phone:	
Contact Email:	
Assembly Status	<input type="radio"/> New Installation <input checked="" type="radio"/> Existing <input type="radio"/> Rebuilt <input type="radio"/> Replacement
Location:	Md024
Service::	Domestic
Make::	Wilkins
Model:	975XL
Serial Number:	910050
Size:	1-1/2"
Type::	RPZA
Asse #:	1013

INITIAL TEST: ☒ Pass ☐ Fail

REPAIR FINAL TEST: ☐ Pass ☐ Fail

INITIAL TEST DATE: 2/5/2019

Final TEST DATE:

Shutoff #2 Close Tight: ☒ Y ☐ N

SHUTOFF #2 CLOSE TIGHT:

CV 1 Close Tight: ☒ Y ☐ N 8.0 PSID

CHECK #1 CLOSE TIGHT: ☐ Y ☐ N

CV 2 Close Tight: ☒ Y ☐ N 2.0 PSID

CHECK #2 CLOSE TIGHT: ☐ Y ☐ N

RPZ Relief Open: 2.6 PSID

RPZ RELIEF OPEN PSID:

PVB Open: PSID

PVB OPEN PSID:

Line Pressure: 130 PSI

Air Gap OK: ☒ Y ☐ N

Comments

Tester License #: MD 12654

Gauge: Mid-West 845-5

Tester Name: Brian Douglass

Serial Number: 10172721

Signature: Brian Douglass

Last Calibration: 10/31/2018