

Additional Funding Request

Submitted: 11/27/2019

MD066 – install drain line in cooling tower	CSS #22599 WO #11416
Description of Repairs	Need to install a drain line in the cooling tower for proper upkeep.
Diagnosis: Initial Work Order	S & S proposes to drain the cooling towers. S & S will then install a new drain line to the plugged outlet at the bottom of the cooling tower and run the piping away from the building and towards the parking lot.
Diagnostic Fee	\$200.00
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	Labor: \$800.00 Plumbing Labor Rate /8 hours/ Rate \$100.00 per hour = \$800.00
Additional Material Cost to Perform Repairs	Materials: \$176.86 Material (see attached detail)
Total Cost of Repair	\$1,176.86