

## OVER AND ABOVE FUNDING

**Region:** 5

**Location:** MD066

**CSS #** 30439

**Maximo Work Order No.:** 14165

**Asset #:** NA

**Date Issued:** 05/08/2021

**Original Description:** MEP & POV Lights need to install 3" Fernco cap on all light poles to prevent water intrusion / damage

**Repairs Needed:**

S&S was onsite and replaced a bad fuse in the pole light and it is now working but Rick asked us to quote to cap all pole lights. S&S proposes to cap all pole lights to stop any water or debris from getting in.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Parts ( See detail attached Quote)	--	--	\$592.21	--	\$592.21
--	NA	SS Labor	20	\$100.00	--	--	\$2,000.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
20	\$2,000.00	\$125.58	\$466.63	\$2,592.21	106%	<b>\$2,747.74</b>