

## OVER AND ABOVE FUNDING

**Region:** 5

**Location:** MD066

**CSS #** 31623

**Maximo Work Order No.:** 14555

**Asset #:** NA

**Date Issued:** 08/02/2021

**Original Description:** Circuit 1 Compressor in Alarm, High Head pressure

**Repairs Needed:**

S&S proposes to remove and replace the Scroll Copeland compressor on Circuit 1. S&S will then complete a system check to ensure the system is working properly.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Parts ( See detail in attached Quote)	--	--	\$3,482.21	--	\$3,482.21
--	NA	SS Labor	20	\$100.00	--	--	\$2,000.00
--	NA	Diagnosis	1	\$250.00	--	--	\$250.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
21	\$2,250.00	\$3,482.21	NA	\$5,732.21	106%	<b>\$6,076.14</b>

